




Navigation Channel Condition Status Report - April 24, 2019



Dredge Status:

Dredge Potter: Docksider / maintenance.

Dredge Goetz: Departed District.

Channel Marker Status:

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.

For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.

Pathfinder The Pathfinder will be dockside over the next week.

Additional Risks / Concerns

Navigation Notices

Local Notice to Mariners

There are advisories for the Miss. and IL Rivers for HIGH RIVER STAGES. Find them here. Buoys may be missing due to high water.

Weather

Highs from the low 60s to the low 80s, lows from the low 40s to the low 60s. Chance of rain throughout the week; stronger chance to the north.

Hannibal, MO

St. Louis, MO

Cape Girardeau, MO

Cairo, IL

Web Information

For additional River Training Structure information, see the links below:

Current Construction

Recently Completed Construction

For open Regulatory Public Notices, See the link below:

Regulatory Public Notices

For the most recent channel patrol and pre or post dredge surveys, see the links below:

Channel Patrol Surveys

Dredge Surveys

Electronic Navigation charts for the Upper Mississippi River are available online for download or to order at the below link:

Electronic Charts

More Status Reports

Click for older status reports

Key:		Probable Dredge Areas				
		River Mile	Problematic On:	Dredge ETA	Dredge Complete	Dredge
⊕	Current Construction Location					
◆	Anticipated Dredging Locations					
☆	Groundings					
△	Dredge Potter					
▽	Dredge Goetz					
○	Fisher					
Very Likely to be Problematic at Low Water						
Could be Problematic at Low Water						
Problem Resolved/Not Problematic						
Please email comments or suggestions to mvsnavstatus@usace.army.mil						